





































Entry Wall Name	Address	Structure	Garden	Comments	
Arroyo Place	Arroyo Place and the Esplanade Caroline Springs	<ul style="list-style-type: none"> <li>Compliant</li> </ul>		Grass growing around the walls. Rusted steel is in good condition.	
Arroyo Place	Arroyo Place and the Esplanade Caroline Springs	<ul style="list-style-type: none"> <li>Compliant</li> </ul>		Sign is rusted steel is in good condition.	
Arnolds Creek	Bullmans Road West Melton	<ul style="list-style-type: none"> <li>Compliant</li> <li>Faded</li> </ul>			
Bluebell Court Entry	Bluebell Court and Trentwood West Melton	<ul style="list-style-type: none"> <li>Compliant</li> <li>Faded</li> </ul>		Rock wall is in good condition.	
Botanica Springs	Botanica Springs Brookfield	<ul style="list-style-type: none"> <li>Compliant</li> <li>Faded</li> </ul>		This wall has a rusted look. It has a water feature which is not operating. The render section needs a coat of paint.	
Bungaree Park	Bungaree Track and Burke Tenterfield	<ul style="list-style-type: none"> <li>Compliant</li> </ul>		Rock wall in good condition the letter A is missing from (Park).	

Entry Wall Name	Address	Structure	Garden	Comments	
Burnside	Westwood Drive and Western Highway	<ul style="list-style-type: none"> <li>Compliant</li> </ul>	<ul style="list-style-type: none"> <li>Renovation required</li> </ul>	Rock wall in good condition rendered could do with a paint. Not on Council land and is privately owned.	
Brookside Village	Rockbank Middle Road and Hepburn Way Caroline Springs	<ul style="list-style-type: none"> <li>Faded</li> </ul>		Wall in good condition. Rendered section needs repainting.	
Banchory Avenue	Banchory Avenue and Melton Highway	<ul style="list-style-type: none"> <li>Compliant</li> </ul>		Wall in good condition. Not necessarily linked directly to the estate a landscape feature in its own right.	
Caroline Springs	Rockbank Middle Road and Acheron	<ul style="list-style-type: none"> <li>Compliant</li> <li>Faded</li> </ul>		Structurally wall is in good condition, but needs a fresh coat of paint.	
Caroline Springs	Calder Park Drive and Taylors Road	<ul style="list-style-type: none"> <li>Compliant</li> <li>Faded</li> </ul>		Structurally wall is in good condition, but needs a fresh coat of paint.	
Caroline Springs	Western Highway and Gourlay Road	<ul style="list-style-type: none"> <li>Compliant</li> </ul>		O.S.I.T have planted the garden bed and given the wall a fresh coat of paint	







Entry Wall Name	Address	Structure	Garden	Comments	
Chisholm Park	Caroline Springs Boulevard and Chisholm Springs South Wall	<ul style="list-style-type: none"> <li>Compliant</li> <li>Faded</li> </ul>		Wall in good condition. Could use a coat of paint.	
Chisholm Park	Caroline Springs Boulevard and Chisholm Caroline Springs North Wall	<ul style="list-style-type: none"> <li>Compliant</li> <li>Faded</li> <li>Cracked</li> <li>Missing parts</li> </ul>		The letters are fine but one of the highlights is hanging off. Needs a fresh coat of paint.	
Cobblestone Village	Cnr Lanaghan and Rockbank Road	<ul style="list-style-type: none"> <li>Faded</li> </ul>	<ul style="list-style-type: none"> <li>Missing plants</li> </ul>	Wall in good condition. Needs a fresh coat of paint.	
Cobblestone Village	Caroline Springs Boulevard and Anderson Avenue North South	<ul style="list-style-type: none"> <li>Faded</li> </ul>	<ul style="list-style-type: none"> <li>Maintenance required</li> </ul>	Wall in good condition. Needs a fresh coat of paint.	
Cobblestone Village	Cnr Rockbank and Hughes	<ul style="list-style-type: none"> <li>Faded</li> </ul>	<ul style="list-style-type: none"> <li>Maintenance required</li> </ul>	Wall in good condition. Needs a fresh coat of paint.	
Cypress Views	Cnr The Avenue and Caroline Springs Boulevard	<ul style="list-style-type: none"> <li>Faded</li> </ul>		Wall in good condition. Needs a fresh coat of paint.	

Entry Wall Name	Address	Structure	Garden	Comments	
Cypress Views	Taylor's Road and The Entrance	<ul style="list-style-type: none"> <li>Faded</li> </ul>		Wall in good condition. Needs a fresh coat of paint.	
Cypress Views	Corner The Broadway and Commercial Road	<ul style="list-style-type: none"> <li>Faded</li> </ul>	<ul style="list-style-type: none"> <li>Maintenance required</li> </ul>	Wall in good condition. Needs a fresh coat of paint.	
Cypress Rise	Beattys Road Hillside	<ul style="list-style-type: none"> <li>Faded</li> </ul>		Wall in good condition. The words have rusted and faded.	
Darlingsford	Barries Road and Darlingsford Road			Wall in good condition. Doesn't have plants in front but could be an improvement project for O.S.I.T.	
Diggers Rest Entry Wall	Plumpton Road Diggers Rest	<ul style="list-style-type: none"> <li>Compliant</li> </ul>		Wall in good condition.	
Earlington	Westwood Drive and Roycroft South			Rendered section needs to be painted.	







Entry Wall Name	Address	Structure	Garden	Comments	
Earlington	Westwood Drive and Roycroft North	<ul style="list-style-type: none"> <li>Faded</li> </ul>	<ul style="list-style-type: none"> <li>Maintenance required</li> </ul>	Rendered section needs to be painted.	
Earlington	Westwood Drive and Fairweather	<ul style="list-style-type: none"> <li>Faded</li> </ul>	<ul style="list-style-type: none"> <li>Maintenance required</li> </ul>	Rendered section needs to be painted.	
Earlington	Westwood Drive and Earlington Boulevard North South	<ul style="list-style-type: none"> <li>Faded</li> </ul>	<ul style="list-style-type: none"> <li>Maintenance required</li> </ul>	Rendered section needs to be painted.	
Encore	Annecy Boulevard Plumpton			Rusted sign in good condition.	
Eynesbury	Cnr Eynesbury Road and Greigs Road	<ul style="list-style-type: none"> <li>Compliant</li> <li>Missing parts</li> </ul>		Wall in good condition. Timber sign needs restaining and the letters painted.	
Edenfield	Taylors and Botanical Drive Caroline Springs			This wall is in great condition requires nothing.	







Entry Wall Name	Address	Structure	Garden	Comments	
Five Ways	Cnr Parwan Exford Road and Griegs Road	<ul style="list-style-type: none"> <li>Missing parts</li> </ul>	<ul style="list-style-type: none"> <li>Maintenance required</li> </ul>	Garden beds all around. Mulch hasn't been finished. Garden bed could be topped up. This is an old timber sign. Looks ok.	
Grandview Park	Cnr The Parks and Banchory	<ul style="list-style-type: none"> <li>Compliant</li> <li>Faded</li> </ul>		Wall in good condition but it needs a fresh coat of paint.	
Hillside 2000		<ul style="list-style-type: none"> <li>Missing parts</li> <li>Faded</li> </ul>		Wall in very poor condition should be removed.	
Holydale Court	Holydale and Trentwood West Melton	<ul style="list-style-type: none"> <li>Compliant</li> <li>Faded</li> </ul>		Rock wall is in good condition.	
Highfield Park	Coburns Road West Melton	<ul style="list-style-type: none"> <li>Compliant</li> </ul>		Wall is in good condition.	
Inglewood Park	Inglewood and Yellow Gum Tenterfield	<ul style="list-style-type: none"> <li>Compliant</li> </ul>		Wall has been repaired previously requires further attention.	







Entry Wall Name	Address	Structure	Garden	Comments
<b>Kurunjang</b>	Melton Gisborne Road	<ul style="list-style-type: none"> <li>Compliant</li> <li>Faded</li> </ul>		This is a timber sign that is in poor condition. It should be removed.
<b>Kilarney Lakes</b>	Kilarney and Sherwin Court Melton	<ul style="list-style-type: none"> <li>Needs maintenance</li> </ul>		Sign is in great condition.
<b>Melton Highway City Bound</b>	Western Highway Melton Bacchus Marsh Inbound	<ul style="list-style-type: none"> <li>Compliant</li> <li>Faded</li> </ul>		Missing a few rocks. Sign is fading.
<b>Melton Entry Wall</b>	Melton Highway City Bound	<ul style="list-style-type: none"> <li>Compliant</li> </ul>		The rock wall is average, a few missing rocks. Flag pole is damaged at the base.
<b>Micassa Rise</b>	Coburns Road and Scarlet Oak		<ul style="list-style-type: none"> <li>Maintenance required</li> </ul>	Wall in good condition.
<b>Muscat Avenue</b>	Muscat Avenue and Taylors Road Burnside Heights	<ul style="list-style-type: none"> <li>Compliant</li> </ul>		Centre median needs more plants.







Entry Wall Name	Address	Structure	Garden	Comments	
Modeina	Westwood Drive and Lexington Drive Burnside	<ul style="list-style-type: none"> <li>Faded</li> </ul>		Timber sign in good condition. Rendered section needs a paint.	
Northgate	Heysen Parkway Caroline Springs	<ul style="list-style-type: none"> <li>Faded</li> </ul>	<ul style="list-style-type: none"> <li>Maintenance required</li> </ul>	Wall in good condition. Outside rendering fading. Needs more plants.	
Oakwood	Woodbury Gourlay Road	<ul style="list-style-type: none"> <li>Faded</li> </ul>	<ul style="list-style-type: none"> <li>Maintenance required</li> </ul>	Wall in great condition. Trees need lifting.	
Parkwood Green Hillside	Melton Highway and Panorama Drive Hillside			This entry wall was badly damaged during the year of 2019. O.S.I.T replanted and painted the wall.	
Peppermint Grove	Mint Boulevard and Bullmans Road West Melton			Wall looks great. Plants in the bed need replacing. One plant is growing to big on one side.	
Pennyroyal	Coburns Road		<ul style="list-style-type: none"> <li>Needs maintenance</li> </ul>	Wall in good condition. Has a rusted look.	









Entry Wall Name	Address	Structure	Garden	Comments	
Parkside Village	Caroline Springs Bellfield Avenue	<ul style="list-style-type: none"> <li>Faded</li> </ul>		Walls are structurally fine, but could do with a fresh coat of paint.	
Parkside Village	Parkway and Bridgewater	<ul style="list-style-type: none"> <li>Faded</li> </ul>		Walls are structurally fine, but could do with a fresh coat of paint.	
Parkside Village	Rockbank Middle and The Parkway	<ul style="list-style-type: none"> <li>Faded</li> </ul>		Wall in good condition. Could use a coat of paint and have missing letter replaced.	
Parkside Village	Caroline Springs Boulevard and Springlake	<ul style="list-style-type: none"> <li>Faded</li> </ul>		Walls are structurally fine, but could do with a fresh coat of paint.	
Riverina	Clarks and Riverina Boulevard Brookfield	<ul style="list-style-type: none"> <li>Missing parts</li> <li>Faded</li> </ul>		Wall is not in great condition on one side.	
Regency Rise	Corner Melton Highway and Royal Parade	<ul style="list-style-type: none"> <li>Faded</li> </ul>		Concrete pillars are stable and in fair condition. Minor damage from tape has occurred and moss on capping.	

Entry Wall Name	Address	Structure	Garden	Comments	
Springlake Village	Cairn Curran and Springlake Caroline Springs			Wall in good condition.	
Springlake Village	Bellfield and Caroline Springs Boulevard			Wall in good condition.	
Springlake Village	Caroline Springs Boulevard and Springside Avenue	<ul style="list-style-type: none"> <li>Faded</li> </ul>	<ul style="list-style-type: none"> <li>Maintenance required</li> </ul>	Wall is faded needs to be painted.	
Stone Ridge			<ul style="list-style-type: none"> <li>Maintenance required</li> </ul>		
Stonybrook	Melton Highway Stonybrook Way				
Strathulloh	Cnr Redgum & Griegs Road	<ul style="list-style-type: none"> <li>Cleaning</li> <li>Sandstone</li> </ul>		Fairly basic sign on fence looks ok pillars on each side. Rocks covered in moss. Could be pressure washed and painted. Remove dead tree.	

Entry Wall Name	Address	Structure	Garden	Comments	
<b>Sugargum Estate</b>	Gourlay Road and Melton Highway	<ul style="list-style-type: none"> <li>Needs maintenance</li> <li>Faded</li> </ul>		Very old looking should be decommissioned.	
<b>The Bellevue</b>	Bellevue BVD and Melton Highway	<ul style="list-style-type: none"> <li>Needs maintenance</li> </ul>		Wall in good condition. Wall on the eastern side was replaced in 2018. Some walls cracking along mortar.	
<b>The Bridges</b>	Bridgewater and Springlake Caroline Springs	<ul style="list-style-type: none"> <li>Faded</li> </ul>	<ul style="list-style-type: none"> <li>Maintenance required</li> </ul>	Wall is in great condition. Wall could use a coat of paint.	
<b>Taylor's Hill</b>	Several Entry Walls Pacific Boulevard/Taylor's Hill Boulevard/Gourlay & Taylor Road/Kirribilli Boulevard/Taylor's & Calder Park Drive	<ul style="list-style-type: none"> <li>Compliant</li> <li>Faded</li> </ul>		Sign is faded. Replacement sign to conform to Council style guide.	
<b>Tenterfield</b>	Tenterfield Drive and Taylor's Road	<ul style="list-style-type: none"> <li>Parts broken</li> </ul>		Very large aluminium structure some of the letters have come away and are close to falling off.	
<b>The Bridges</b>	Rockbank Middle Road Lauriston Quay	<ul style="list-style-type: none"> <li>Faded</li> </ul>		The rendered walls and timber but it needs a fresh coat of paint. Dead plants need to be removed.	

Entry Wall Name	Address	Structure	Garden	Comments	
The Close	The Close and Bridgewater Caroline Springs	<ul style="list-style-type: none"> <li>Compliant</li> <li>Faded</li> </ul>		Needs a fresh coat of paint.	
The Grove	Caroline Springs Boulevard and The Grove	<ul style="list-style-type: none"> <li>Compliant</li> <li>Faded</li> </ul>		Needs a fresh coat of paint.	
The Grove	Rockbank Middle and Naracourt Caroline Springs	<ul style="list-style-type: none"> <li>Compliant</li> <li>Faded</li> </ul>		Wall in good condition. Needs a fresh coat of paint.	
The Grove	Rockbank Middle Road and St Georges	<ul style="list-style-type: none"> <li>Compliant</li> <li>Faded</li> </ul>		Wall in great condition. Needs a fresh coat of paint. Trees are too big for the space and are blocking the sign.	
The Grange	The Crossing Caroline Springs			The wall is in great condition.	
The Parks	Melton Highway and The Parks	<ul style="list-style-type: none"> <li>Faded</li> </ul>		O.S.I.T have replanted and given the wall a fresh coat of paint in 2020.	

Entry Wall Name	Address	Structure	Garden	Comments	
<b>Toolern Downs</b>	Buckle Road and Melton Gisborne Road			Timber sign in good condition.	
<b>Victoria Grove</b>	Kirkton Drive Kuranjang			Great condition.	
<b>Watervale</b>		<ul style="list-style-type: none"> <li>Faded</li> </ul>		Needs a fresh coat of paint. Missing paver needs to be replaced.	
<b>Westlake</b>	Westlake Drive Bullmans West Melton	<ul style="list-style-type: none"> <li>Needs maintenance</li> </ul>		Wall solid and intact	
<b>Woodgrove Walk</b>	Corner Fairhaven Street and High Street West Melton	<ul style="list-style-type: none"> <li>Faded</li> </ul>	<ul style="list-style-type: none"> <li>Maintenance required</li> </ul>	Needs a fresh coat of paint.	
<b>Woodgrove Walk</b>	Trethowan and Fairhaven		<ul style="list-style-type: none"> <li>Maintenance required</li> </ul>	Wall in great condition.	

Entry Wall Name	Address	Structure	Garden	Comments	
Willandra	Willandra Boulevard and Coburns Road	<ul style="list-style-type: none"> <li>• Compliant</li> <li>• Missing parts</li> </ul>		Wall in good condition. Missing several letters.	