

Appendix 2 – Grounds for refusing to extend the life of the permit

- (1) The earthworks and fill carried out on the subject land is inconsistent with planning permit (PA2015/4962) issued and granting an extension of time permit will not result in an acceptable outcome.
- (2) There appears to have been no attempts made to enact the permit in accordance with the endorsed plans.
- (3) The time limit originally imposed on the permit have given sufficient time for the permit to be enacted, and the works to be completed.