

Diggers Rest Recreation Reserve Progress Update



Gravel mound for Oval 2 drainage layer

SNAPSHOT

Oval progress

Irrigation shed

Pavilion slab preparation

Cricket nets earthworks

Oval 2...

Progress has been steady on Oval 2. The large mound of gravel in the photo above is slowly being spread across the oval. This will provide part of the drainage system required for optimum playing surface in wet weather. The drainage pipework and irrigation are almost complete. And the new shed for the pump is built (and has already been broken into, so please keep an eye out if you're in the area). Subject to ongoing weather conditions, the turf is now expected to be laid in January.

Cricket Nets...

The area has dried out enough for the works to commence and we should see this lots of progress in December.



Nov '22– waterlogged pavilion

The nets are in the construction zone, so they won't be open until the surrounding areas are open to the public.

Pavilion...

Despite improved weather conditions, the pavilion has not progressed as much as planned. The contractors are working through some issues and we're closely monitoring and providing assistance where possible. We'll provide further updates on any impacts.